

Mother Iveys

Engineer Assessment Form

Assessment Completed By:	Steve
Date of Assessment:	4/9/24
Time of Arrival:	
Time of Departure:	
JIRA Reference	Quot-4000
SAGE Quote No.	
Work Code	
Van Make	Atlas plot 489
Van Model	2018 onyx
Van Serial Number	AT014465/08
Van Stock Number	
Van Size	
Quote Information	water getting in and a wall board has got water damage and is rotten. They would like a quote for a replacement wall board left hand side of the main door, The owner has also reported this weekend that the floor by the door has started to go soft.
Description of the Issue Including the Following: <ul style="list-style-type: none"> • Internal or External? • Which Room of the Caravan/ Which Panel? • Which Parts does the issue affect? • Plus any other useful information 	window / Door frame leaking probably top edge of window / panel joint to be sealed when doing wall board / floor Floor to be replaced in main doorway between beds cupboard + dining chairs approx 2m x 600 X/ wall board X/ sheet of flooring 1 Man 1 Day
What is the cause of the issue?	