

Carlyon Farm PL27 6RJ

Engineer Assessment Form

Assessment Completed By:	
Date of Assessment:	
Time of Arrival:	
Time of Departure:	
JIRA Reference	Quot-4154
SAGE Quote No.	
Work Code	
Van Make	swift
Van Model	Auvergne plot 21
Van Serial Number	
Van Stock Number	
Van Size	
Quote Information	Bathroom window is leaking, assessor from insurance company put hose up against window, floor has gone spongy, customer would like a quote for us to repair Ian Wedge 07742604844
Description of the Issue Including the Following: <ul style="list-style-type: none">• Internal or External?• Which Room of the Caravan/ Which Panel?• Which Parts does the issue affect?• Plus any other useful information	Bath room floor soft need replacement agreed to support shower with extra joists as do not wish to remove shower Need to remove window section floor to ceiling rescal and refit Also rescal all window tops end door side Also to add extra joist from w/ back cupboard to front of van to support slightly soft floor about 6 meters in length
What is the cause of the issue?	Customer to supply vinyl for bathroom floor 2 Sheets 8'x4' 1 1/2 Days 2 men

Opening window sash is leaking over top of window really needs extra protective drip as window is warped