Warranty Claim Job Sheet

Claim No:	W0222591	Repair / Inspect	
Serial No:	2230092		
Description:	HAMILTON 36.12 (2B) 2024		
Run No:	H4312A		
Build Date:	19/09/2023		
Despatch Date:	17/06/2024		
PDI:	☐		
Date Acknowledged:	08/07/2024 09:54:19		
Acknowledged By:	Amy Clark-Blakey		
Date Completed:			

Area:	**A14**
Dealer:	3T'S LEISURE LTD T/A
Site No:	51
Site:	GOLDEN CAP CARAVAN PARK
	GOLDEN CAP CARAVAN PARK SEATOWN CHIDEOCK DORSET DT6 6JX
Site Phone:	01297480010

Key Number:	174 135
Plot Number:	368
Contact On Site:	Jen
Owner:	
Date of Sale:	
Sale Type:	Unsold

Special Notes:

Has the Owner of the van given permission / full consent for ABI UK Engineers / External Companies working on behalf of ABI to enter the said unit to complete the following work and any follow up work?

Please note work cannot commence until this document is signed.

Sign: James Eginton **Print:** James Eginton **Date:** 05/07/2024

Parts

No:	Issue:	Location:	Position:	Description:
1	Faulty	Bathroom	Back End	The bathroom blind string is twisted and restricts the blind function from working and wand is missing. Pic 1,2,3
2	Faulty	Bathroom	Back End	The packing tape has bleached in the sun and left glue residue on some of the furniture and mirrors Pic.4,5
3	Damaged	External	Back End	The front exterior barge board is damaged on both corners possibly Transport Damage Pic 6,7,8 *** REJECTED DAMAGE NOT COVERED UNDER WARRANTY **

CurrentStatus: Rejected

Rejected by Amy Clark-Blakey on 08 Jul 2024