

SURF BAY LEISURE Assessment Sheet

WORK CODE: 403 LOG NO: QUOT-3197 MAKE: Quotes MODEL: Willerby Herald Gold 2010 SIZE: SERIAL NO: STOCK NO: Assigned to Charleen Sibley	ADDRESS: (558) JB Old Ltd, t/a Treyarnon Bay Caravan Park St Merryn Padstow PL28 8JP PITCH NO: L17 TEL:
--	---

Problem

Exterior panels are damaged - please assess for repair - Photo of damage attached.

Details of Work To Be Done

Replace 2 exterior panel (Sandstone)
 Replace Corner Capping
 Replace Angled panel beside front window
 Replace wall board inside of van
 Replace foam Seal on windows (Screwfix)

Parts Needed

Remove window on front corner of van replace 2 panels
 Remove lower panel to allow access to panel above + refit
 + Corner Cappings + refit windows + reseal ~~new~~

panels x 2 1150^H x 2.800 200 x 800^H profile No 4

wall board x 1

Corner Capping 30mm x 30mm

window Side panel (Angled) 150^H x 25mm
 ← with rolled edges

How long / how many engineers

1 1/2 Day 2 Men

ARRIVAL TIME	
DEPARTURE TIME	
DATE	

(Quote to be emailed to
 Emma who will pass
 to the park)

Thanks!