

WORK CODE 403
LOG NO: QUOT-3197
MAKE Quads
MODEL Willeby Herald Gold 2010
SIZE
SERIAL NO
STOCK NO
Assigned to Charleen Sibley

ADDRESS (558)
JB Old Ltd, Va Treyarnon Bay Caravan Park
St Merryn
Padstow
PL28 8JP
PITCH NO L17
TEL:

Problem

Exterior panels are damaged - please assess for repair - Photo of damage attached.

Details of Work To Be Done

Replace 2 exterior panel
Replace Corner Capping
Replace Angled panel beside front window
Replace wall board inside of van
Replace foam Seal on windows (Screwfix)

Parts Needed

Remove window on front corner of van replace 2 panels
Remove lower panel to allow access to panel above + re-bit
+ Corner Cappings + re-fit windows + reseal

panels x 2 1150^h x 2.800 200 x 800 w profile 1004

Wall board x 1

Corner Capping 30mm x 30mm

Window Side panel (Angled) 150^h x 25mm with rolled edges

How long how many engineers

1 Day 2 Man

ARRIVAL TIME	
DEPARTURE TIME	
DATE	