

WORK CODE: 403	ADDRESS: (558)
LOG NO: QUOT-3197	JB Old Ltd, 1/3 Treymon Bay Caravan Park
MAKE: Quora	St Merryn
MODEL: Wilberby Herald Gold 2010	Padstow
SIZE:	PL28 BJP
SERIAL NO:	PITCH NO: 617
STOCK NO:	TEL:
Assigned to: Charleen Sibley	

Problem  
Exterior panels are damaged - please assess for repair - Photo of damage attached.

Details of Work To Be Done

- Replace 2 exterior panel
- Replace Corner Capping
- Replace Angled panel beside front window
- Replace wall board inside of van
- Replace foam Seal on windows (Screwfix)

Parts Needed

Remove window on front corner of van replace 2 panels  
Remove lower panel to allow access to panel above + re-fit  
+ Corner Cappings + re-fit windows + reseal

panels x 2 1150" x 2.800 200 x 800 # profile no 4

Wall board x 1

Corner Capping 30mm x 30mm  
window Side panel (Angled) ← with rolled edges  
25mm  
How long how many engineers

1 Day 2 Man

ARRIVAL TIME	7:30 AM
DEPARTURE TIME	6:30 PM
DATE	3/12/20