

LEAK

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 428 LOG NO: SWIFT-19164 MAKE: Swift MODEL: Moselle Lodge SIZE: 40 X 13 SERIAL NO: 022268H STOCK NO: 32492 Assigned to Adrienne Barwell	ADDRESS: (555) Trewince Farm Holiday Park St Issey Wadebridge PL27 7RL PITCH NO: 78 TEL:
--	--

Problem

Master Bedroom - The top right corner of the window is leaking in water where the frame fits the body. Please try to re-seal. *customer has advised water is running down the wall*

Notes:

Details of Work Done

Foam along ridge has become displaced allowing driving rain etc to enter behind roof sheet. ~~Rain~~ Water then runs down moisture barrier to external wall and finds its way out from window space etc. Have stuck foam back into position with silicon have also silicon sealed window vent and side of window which is most exposed to driving weather conditions.

ARRIVAL TIME	10:00
DEPARTURE TIME	11:45

DATE: 1/5/18 FITTER: *MAN PETERS*

I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE

PARK/CUSTOMER SIGNATURE:

MATERIALS USED	NOTES

* Have informed the son of van owner where I think leak is occurring and works done, and to keep an eye out to see if this has rectified problem