

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- **DATE**-----

POSITION-----

WORK CODE: 403 LOG NO: QUOT-4047 MAKE: Swift MODEL: Bordeaux SIZE: 33x12 2B SERIAL NO: 024730h STOCK NO: Assigned to Charleen Sibley	ADDRESS: Nichols Nymett Holiday Park North Tawton EX20 2BP PITCH NO: 27 TEL: 01837 82484
---	---

Problem

Repair water ingress offside rear corner area
Mr Race and Mike at park phoned to advise that the van keeps tripping and have had an electrician find that the main bedroom far offside rear socket to be very wet and rusty, electrician has said he thinks the gutter bracket is inline with the socket and could be a possible cause, I have advised we will come and take a look and fix onsite if we can or make an assessment for a quote if required. Electrics have been isolated in this area until we have completed our work.
Notes: <p style="text-align: center; font-size: 1.2em;">Can't see any issue with brackets</p>

Details of Work Done

<p style="font-size: 1.1em;">Corner Capping bit short so if water goes over edge of gutter could find its way inside corner capping Have sealed lap edge of corner capping no issue with anything else</p>
--

ARRIVAL TIME	15:00
DEPARTURE TIME	16:05

DATE: 10/12/24	FITTER: Steve
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES