


						Comments
Heater						
Heater/ Combi Boiler	—					
Heater Cowl	—					
Hallway						
Door	—					
Carpet/ Lino / Trim	—					SEE MISC COMMENTS
Kick / Skirting Boards			—	—	—	
Door Handles & Latches	—					
Wall Boards			—	—	—	RH of Ewin bed door & End wallboard before joint in Lodge both boards bubbled / ripped
Radiators/ Electric Panel Heater	—					
Ceiling Boards	—					
Wall Ceiling Lights, Bulbs, Spots & Shades	—					
<i>ELECTRICAL Panels</i>			—	—	—	MISSING ELECTRICAL INSPECTION Panels ALONG TWIN bed door
General						
Carbon Monoxide Alarm						
Smoke Alarm						
Exterior						
Chassis	—					
Wheels/ Tyres	—					
Corner Steadies	—					
Jockey Wheel/ A Frame	—					
Panels	—					
Windows to be opened, checked & adj	—					
Doors - locked/unlocked <i>adjusted</i>	—		—	—	—	REQUIRES ADJUSTMENT
Door Handles / hinges x? / Colour? <i>BLK</i>	—					
Door Retains	—					
Exterior / Spot Lights	—					
Down Pipes	—					
Gutters/ Brackets / Colour?	—					
Roof	—					
<i>Joint Trim</i>				—	—	Rear Joint Trim Gipped / marked
Miscellaneous						
<i>Trims</i>			—	—	—	1x Length of Beam capping missing - Hallway 2x Lengths of skirting required as parts supplied too short or missing 1x Length of cornice required as short in Hallway



I hereby agree that Surf Bay Leisure have undertaken a Pre-Occupation Inspection on the above caravan and accept and agree with the findings shown above and confirm apart from those mentioned there are no items missing, damaged, or that require attention.

Park Signature.....Date.....