

+ Sealant cost and travel.
Reseal same panel screws.

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: LOG NO: QUOT-4246 MAKE: Quotes MODEL: roxbury SIZE: 38x12 SERIAL NO: 1750311 STOCK NO: 30117 Assigned to James Eginton	ADDRESS: North Upton Farm Bantham Kingsbridge TQ7 3AB PITCH NO: 25 (6 th up on 4/4/s by red fire box). TEL: 01548 560508
--	---

Problem

Leak coming into the bathroom, appears to be coming down the cladding wall - ASSESSMENT

Notes:

Details of Work Done

look like window is leaking in around seal to ven
could also be panel screws, also gutter looks like its leaking
above window on joint
Remove window + reseal + panel screws 3 hours 1 man

ARRIVAL TIME	900
DEPARTURE TIME	230

DATE: 6/3/26	FITTER: Steve
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES