

SURF BAY,

Shower has crack under  
where tape is.

The shower tray is one  
that yourselves replaced  
about 3 years or so ago.

When you quote can you  
also allow please for  
extra wood strengthening  
underneath to try & prevent  
this happening again.

The shower tray has always  
had some give to left of  
play hole & if extra  
strengthening could be done  
it should help.

Thank you

Mike Menhitt

MIKE MENHITT