

PADSTON TOURING PARK 15.1.15

- The hob racks seem to be bent and sit close to burners they also have chips in the enamel - ORDR NEW
- shower cubicle back and side do not sit flush to the walls but "bow" - NOTE
- out into the cubicle - just a little concerned of any wet getting behind the sides if this isn't correctly fitted?
- The grill is still not working, correctly, lights but will not stay on when knob is released - NEW THERMO COUPLE
- Front door is not lined up correctly you can see day light in corner - DONE
- Light switch in lounge doesn't work correctly hard to switch on and off - DONE
- Door handles on TV unit/Boiler unit/Cupboard are not level - PHOTO
- Mirror in lounge has black marks on the frame - ORDR NEW
- Stool is bent and needs a rubber stopper - DONE
- Velcro fastenings in dining area - DONE
- No caps on screws in shower - DONE
- Right hand switch in lounge doesn't work properly - DONE

NOTE SHOWER SIDE - DOUBLE SIDED TAPE COMING AWAY
MAY NEED SCREWS + CAPS TO SECURE

