

SURF BAY LEISURE AFTERSALES ASSESSMENT SHEET

Completed By:		
Arrival Time		
Departure Time:		
Work Code		Address:
Log No.	QUOT-1783	(206)
Make	Quotes	Golden Cap Caravan Park
Model	Atlas Amethyst (2004)	Seatown, Chideock
Size		Bridport
Serial No.		DT6 6JX
Stock No.		
Pitch No.	209	Tel:01297480010
Notes:	Mr Weaver has reported that he has some water ingress which he thinks is adjacent to the stretcher roof joints. Alan who he saw when he called in yesterday has asked him to get the park to look at in the first instance. His caravan is on pitch 209 at Golden Cap, he thinks it's a 2004 model, had no idea of serial number. He also asked Alan if it might need reroofing which he's been told is unlikely but it would need to be properly inspected.	
Description:	<p>water ingress along window side gutter / fascia Also water damage in kitchen ceiling board mostly caused by leaking roof vent (now fixed by site) Remove fascia along window side seal gutter joint + Staples in soffit under gutter length of oven</p>	
Parts Required:	<p>3 Tubes Satix U9 1 12ft atlas ceiling board customer will except 1/2 board with joint</p>	
Measurements:		
Estimated Time:	<p>2 men 1 Day to do ceiling board work inside (separate quote) 1 Day to do outside work to make watertight</p>	
Man Power:	2 men	
Photos Taken?	Yes	