

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE----- DATE-----**

**POSITION-----**

WORK CODE: 36291 LOG NO: RET-243 MAKE: Retrofit MODEL: Atlantique SIZE: 35x12 SERIAL NO: 029618h STOCK NO: 36291 Assigned to Stephi Plant	ADDRESS: Not defined <b>Surf Bay Winkleigh</b>  PITCH NO:  TEL:
--	--

Problem

Swap front doors to front window
Notes: Matt has replaced the panels taken for this caravan stock 36291 he has replaced the panels on 35558 028683H <i>- FRONT PANEL ONLY</i> <i>TOO WINDY ON DAY TO FIT REAR PANELS</i>

Details of Work Done

Re built / re-fitted R/H front wall as bottom was sticking out approx 30mm from end of flooring (not secured). Fitted replacement panel, sealed + refitted all trims. Cleared tape residue off external corner cappings, doors + panels.
--

ARRIVAL TIME	10:15 (1/2 hr lunch)
DEPARTURE TIME	14:30

DATE: 18/4/19	FITTER: <i>MATT PETERS</i>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
<b>PARK/CUSTOMER SIGNATURE:</b>	

MATERIALS USED	NOTES

*\* 1 No Corner capping @ 2210mm long, required - (L/H is split at the bottom)*

*Fitted new bottom back panel + 1 Corner Capping  
 Cleared up + glued together x 2 other capping  
 Steve ✓*