


						Comments
Heater						
Heater/ Combi Boiler			—	—	—	Boiler isn't connected Corains
Heater Cowl	—					
Hallway						
Door	—					
Carpet/ Lino / Trim	—					
Kick / Skirting Boards	—					
Door Handles & Latches	—					
Wall Boards	—					
Radiators/ Electric Panel Heater	—					
Ceiling Boards	—					
Wall Ceiling Lights, Bulbs, Spots & Shades	—					
General						
Carbon Monoxide Alarm	—					
Smoke Alarm	—					
Exterior						
Chassis	—					<p> Rub marks from down pipe Clip (missin) DS front + slight bulge in panel RHS of DS front down pipe clip (top of Bottom panel) 1x Down pipe is missing and caused above damage — Replaced missing clip van stock </p>
Wheels/ Tyres	—					
Corner Steadies	—					
Jockey Wheel/ A Frame	—					
Panels	—			—	—	
Windows to be opened, checked & adj-	—					
Doors - locked/unlocked adjusted	—					
Door Handles / hinges x? / Colour? WHT	—					
Door Retains	—					
Exterior / Spot Lights	—					
Down Pipes	—		—	—	—	
Gutters/ Brackets / Colour? WHT	—					
Roof	—					
Miscellaneous						



I hereby agree that Surf Bay Leisure have undertaken a Pre-Occupation Inspection on the above caravan and accept and agree with the findings shown above and confirm apart from those mentioned there are no items missing, damaged, or that require attention.

Park Signature..... Date.....