

Quot- 1554

SITE	St. Andrew Bay
MAKE	Correll
MODEL	Tobay
SERIAL NUMBER	
PITCH NUMBER	557
OUR REF	
DATE	14/3/15
DESCRIPTION	water come in from corner capping outside Swelled up wall board replace wallboard with nearest match available re seal plastic capping
PARTS REQUIRED INCLUDING SIZES	1 wall board kege Caulk 50 x1 tube Silfor / or Sealant
ESTIMATED TIME	4 hours
MAN POWER	1
PHOTOGRAPHS TAKEN	yes