

URGENT

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 428 LOG NO: SWIFT-9299 MAKE: Swift MODEL: chamonix SIZE: 41x12 SERIAL NO: 016133h STOCK NO: 30330 Assigned to Adrienne Barwell	ADDRESS: (567) Unity Farm, Coast Road Brean Burnham on Sea TA8 2RB PITCH NO: E1 TEL:
--	--

Problem

plumbing under the kitchen sink. As you pull the plug from the sink to release the water the weight of the water detaches the waste pipe underneath (as the pipe has been cut too short) and the whole plumbing unit falls off which floods the floor. This has happened 3 times now. The owner has to hold the waste pipe intact whilst his wife pulls the plug to stop it from flooding at the moment. As well as the force of the water un attaching the waste pipe, if you try to fix this it has a knock on effect to the other pipes so there is a constant leak somewhere under the sink. The whole plumbing unit needs replacing. As attached picture

Notes: Swift will not be getting parts to us for this job, please take anything you need from the Chamonix in the yard or buy locally ie D&S make sure you keep a record of what you have taken /purchased

Details of Work Done

Have renewed washers in plumbing under sink nothing is cut short and all parts are correct and does not now leak however under van waste pipe is not supported and is hanging down with weight of water therefore plumbing is pulling joints apart under sink allowing it to leak

ARRIVAL TIME	1030
DEPARTURE TIME	1145

DATE: 2/10/15 FITTER: Stone / Mall

I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE

PARK/CUSTOMER SIGNATURE: *[Signature]*

MATERIALS USED	NOTES