

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE**-----**DATE**-----

**POSITION**-----

WORK CODE: 403 LOG NO: QUOT-1783 MAKE: Quotes MODEL: Atlas Amethyst (2004) SIZE: SERIAL NO: STOCK NO: Assigned to Lorraine Pryor	ADDRESS: (206) <del>Golden Cap Caravan Park</del> <del>Seatown Chideock</del> <del>Bridport</del> <del>DT8 6JX</del> PITCH NO: 209 TEL:
---	---

Over parts in stock

**Problem**

Water ingress which customer thinks is adjacent to the stretcher roof joints-
Jen at park requested we go to assess and quote to repair
Notes;
<b>Can you please check to see if we have the ceiling boards in stock/ silfix etc so I can then issue the work sheet for us to carry out the work?:</b>

**Details of Work Done**

We have 2 boards not best quality anyone may be able to do it with half board
---

ARRIVAL TIME	
DEPARTURE TIME	

DATE:	
I AM HAPPY WITH THE WORK CAR	
PARK/CUSTOMER SIGN.	

MATERIALS USED	

Steve: 11/11/12  
 Can you see if we have parts in stock for this job before I issue a worksheet thank  
 Lorraine