

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE----- DATE-----**

**POSITION-----**

|   |  |
|---|--|
| WORK CODE: 428<br>LOG NO: SWIFT-10051<br>MAKE: Swift<br>MODEL: Bordeaux<br>SIZE: 38x12<br>SERIAL NO: 020530h<br>STOCK NO: 31649<br>Assigned to Adrienne Barwell | ADDRESS: (76) Brradicks Holiday Park<br><b>Merley Road</b><br><br><b>Westward Ho!</b><br><b>EX39 1JS</b><br><br>PITCH NO: Lundy View 105<br><br>TEL: |
|---|--|

**Problem**

PDI reports Robe drawer unit needs a new runner on lower drawer, does not allow smooth action for the drawer, please can you attempt to adjust this and advise whether parts are required.

Wally has reported that the shower drain is not fitted properly, please can you take a look at it and let me know what you have done if anything to rectify this

Loose corner strip in the main bathroom, please try and refit

PDI reports Wall trim Strip above the Master bedroom door is incorrectly fitted please refit

Notes:

**Details of Work Done**

|                |                  |
|----------------|------------------|
| ARRIVAL TIME   | 23 <sup>30</sup> |
| DEPARTURE TIME | 24 <sup>5</sup>  |

|   |               |
|---|---------------|
| DATE: 18/1/16   | FITTER: Steve |
| <b>I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE</b> |               |
| <b>PARK/CUSTOMER SIGNATURE:</b>                                       |               |

| MATERIALS USED | NOTES |
|----------------|-------|
|                |       |
|                |       |