

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 407 LOG NO: SBHP-383 MAKE: Our Parks MODEL: SIZE: SERIAL NO: STOCK NO: Assigned to Adrienne Barwell	ADDRESS: (704) Beachside Holiday Park Merley Road, Westward Ho! Bideford EX39 1JS PITCH NO: various (see Harvey) TEL:
---	---

Problem

peg board under seating is to be replaced with hardboard (7x vans)

 Hardboard already on site, please make contact with Harvey on site for van details
 Also
 The same vans need wooden boards made up to go under the water heaters, (Steve King has a template in his office)
 Please use the Citroen for transport

Notes: 6 no vans complete on seatboards + upholstery
 1 no van to complete = = = =
 7 no vans remaining to fit boiler pipe covers.

Details of Work Done

Cut all seatboards to size + fit (fit support battens where needed)
 Remove upholstery + re-fit to cover seatboard edges.
 Make 6 no Boiler pipe covers
 Make 1 no Boiler pipe covers.
 Remove existing broken staples, damaged boards and all sharp edges.

ARRIVAL TIME	
DEPARTURE TIME	

DATE: _____ **FITTER:** _____
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE
PARK/CUSTOMER SIGNATURE: _____

MATERIALS USED	NOTES