


3-3.30 w+ch
330-5.427

PITCH 97 →
Door

1100 - 2.30
BOTH DOORS -
HAD TO RE FACE + LOWER
VAN ON 6ND
+ LIFT BOTH
DOORS

SURF BAY LEISURE AFTERSALES ASSESSMENT SHEET

Completed By: Date	UR 16.2.16	
Arrival Time	2.30 - 3.00	
Departure Time:		
Work Code	403	Address:
Log No.	QUOT-2079	(594) West Wayland Caravan Park
Make	Quotes	The Bungalow
Model	Everglade	West Wayland
Size		Looe
Serial No.	none given	PL13 2JS
Stock No.		
Pitch No.	58	Tel:01503 262410
Notes:	01843-848571	
Description:	<p>1.Sky light over the shower cubical is loose and flapping/ 2.Strip that holds the panel down is loose → NOT SURE 3.Mr cox has also requested a price for us to Waxoyl his van. WHAT HE MEANS He has the waxoyl but would like us to apply it.(we can only do this is if we use our own waxoyl as top workshop have a machine and we have to use a certain make that goes though the machine)- please access its on cliff - access etc.</p>	
Parts Required:	 <p>FIXED ROOF VENT $6\frac{1}{2}$" $6\frac{3}{4}$" TO SUIT 170mm (6 3/4") HOLE</p>	
Measurements:	<p>* ROOF RIDGE PANELS ARE UNDER VAN PHOTO</p>	
Estimated Time:	<p>1-HR FOR VENT $1\frac{1}{2}$-HR FOR RIDGE TO REPAIR + TRAVEL</p>	
Man Power:		
Photos Taken?		

Labour: £117.00
Labour: £117.00