

SURF BAY LEISURE AFTERSALES ASSESSMENT SHEET

Completed By & Date:	MATT PETERS 26/2/16.	
Arrival Time	12.30	
Departure Time:	13.00.	
Work Code	<u>403</u>	Address:
Log No.	QUOT-2079	West Wayland Caravan Park The Bungalow West Wayland Looe PL13 2JS Tel:01503 262410-
Make	Quotes	
Model	Everglade	
Size	31FT X 10FT.	
Serial No.	none given	
Stock No.		
Pitch No.	58 - Mr Cox	
Notes:	CHASSIS SHOWS SIGN OF EXTENSIVE SURFACE CORROSION WHICH WILL HAVE TO BE REMOVED (SCRAPED/BRUSHED) FROM ENTIRE CHASSIS.	
Description:	<u>Mr cox has also requested a price for us to Waxoyl his van. Can you please take photos of his chassis so we can assess the corrosion to see how good/bad it is. Also can you let me know the size of the van as this needs to be facted into quote</u>	
Parts Required:		
Measurements:	VAN MEASURES 31FT X 10FT.	
Estimated Time:	* SEE BILL PETERS / BILL HIBBS FOR EST TIME. - THEY ARE SKILLED / EXPERIENCED IN DOING THESE JOBS.	
Man Power:	x2.	
Photos Taken?	Yes.	