

Engineer Assessment Form

Mullion Holiday Park, Ruan Minor, Helston, Cornwall TR12 7LJ

SB 74

Assessment Completed By:	Slane
Date of Assessment:	12/4/16
Time of Arrival:	10:00
Time of Departure:	1:15
JIRA Reference	QUOT-2188
SAGE Quote No.	
Work Code	403
Van Make	
Van Model	
Van Serial Number	
Van Stock Number	
Van Size	
Quote Information	<p>Water Ingress - see email attached to worksheet - park want at date when we can attend.</p> <p>(Yes H3 has a similar problem but nowhere near as severe however I think it would be beneficial for it to be assessed - however H12 is the absolute priority as their problem increases day to day)</p>
Description of the Issue Including the Following: <ul style="list-style-type: none">• Internal or External?• Which Room of the Caravan/ Which Panel?• Which Parts does the issue affect?• Plus any other useful information	<p>Shower Tray cracked</p> <p>2 1/2 hours to replace</p> <p>£ 530 in order book</p>

NOTHING Alled in

What is the cause of the issue?			
Basic Materials Required (Please Tick as Applicable and give details)	YES	NO	
Sealant			
Screws			
Flooring V313			
Flooring Celotech			
Wallboards			
Ceiling Boards			
Other (Please Give Details)			
Parts Required			
Part Name	Manufacturer	Part Number	In Stock? (Tick where applicable)
Measurements:			
Man Power:			

NOTHING-filled in

Number of Days/ Hours + Number of Men Required	
Photographs Taken?	
Samples?	
For Office Use Only	
Insurance Company	
Insurance Reference/ Claim Number	
Excess Amount	
Excess Payment Received?	
Assessor Details	
Customer Name:	
Address:	
Telephone:	
Email:	