

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 279393 LOG NO: SBHP-413 MAKE: Our Parks MODEL: Everglade 2008 SIZE: SERIAL NO: STOCK NO: 27393 Assigned to Adrienne Barwell	ADDRESS: (656) River Valley Country Park Relubbus Penzance TR20 9ER PITCH NO: Yellow 18 TEL:
---	--

Problem

Remove front window Woodwork needs to assessed and repaired/ replaced Replace window cill with white plastic Replace wallboard above cill with a neutral board Wax the side part of the corner unit Refit front window Reseal around panel joints

Notes: <i>Steve thinks we have parts to sort this job.</i>
--

Details of Work Done

--

ARRIVAL TIME	<i>1115</i>
DEPARTURE TIME	<i>230</i>

DATE: <i>25/5/16</i>	FITTER: <i>Steve</i>
----------------------	----------------------

I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE

PARK/CUSTOMER SIGNATURE:

MATERIALS USED	NOTES

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE-----**DATE** 10.5.16

POSITION-----

WORK CODE: 27393 LOG NO: SBHP-413 MAKE: Our Parks MODEL: Everglade 2008 SIZE: SERIAL NO: STOCK NO: 27393 Assigned to Adrienne Barwell	ADDRESS: (656) River Valley Country Park Relubbus Penzance TR20 9ER PITCH NO: Yellow 18 TEL:
--	--

Problem

the front window sill has become "spongy" – the site suspect from condensation. Please can you assess this unit and report back.

Notes: I THINK DAMP HAS GOT IN FROM AROUND WINDOW AND PANEL JOINTS JUST ABOVE EACH CORNER .
 THE SMALL SECTION OF WALL BOARD ABOVE CILL IS ALSO ~~ROTTEN~~ ROTTEN

Details of Work Done

LOWGR

WINDOW NEED TO BE REMOVED - POSSIBLY TOP ONE AS WELL
 WOODWORK NEEDS TO BE ASSESSED AND REPAIRED
 CILL AND PLAMING NEEDS TO BE REPAIRED/REPLACED
 NEW CILL NEEDS MAKING + REPLACING
 SIDE PART TO CORNER UNIT WOULD HAVE TO BE WAXED

ARRIVAL TIME	12.45
DEPARTURE TIME	1.30

CILL BOARD



DATE:	FITTER:
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES

NEED CILL BOARD 1600 x 150 x ?? BIGGER THE BETTER
 SMALL PIECE OF WALL BOARD - CRIMBY YELLOW
 TIMBER FOR FRAME WORK - 30 x 30 x 6m
 + SILICONE

1 MAN 3 HRSISH + TRAVEL (OATH DAY)