

# SEVEN BAYS

Steve,  
I have asked Dan  
for a few photo's  
or measurements  
can you get me these.

## URGENT

SOFA BED FOR FRONT ROOM *ordered*

2 WHEELS FOR SINGLE DEVAN BED *ordered*

## Other Snags

-Trim on corner by the living space door on dining room size (floor to ceiling) *ordered*  
NEVER FITTED *(photo) B. bid*

-Finishing caps on breakfast bar (to cover screws) *ordered.*

-Music system has two speakers not working (as well as impossible to tune) *ATLAS. Does not appear to be here*

-Kitchen window blind is broken *ordered Seemed to work? at all*

-door frame on 2nd bedroom NOT GOOD, *ordered Broken*

-Master bedroom door doesn't close *WIS Done ✓*

-wall damaged behind kitchen door in the hallway - *ordered*

-wall damaged above kitchen sink - *ordered - This has been repaired badly*

-panel damaged behind kettle - *can you confirm plain or patterned*  
*Plain (not rock face)*

-light switches in dining area broken (not ever worked) *ordered Done ✓*

-deep scratch on kitchen cupboard door by wine fridge *clarify which one*  
*Small left hand cupboard door*

-deep scratch on door below - *clarify which one*  
*Don't know can't see it*

-kitchen window need adjusting as difficult to close *WIS Done ✓*

-metal strip on living room/ dining room floor (not fixed to anything) *WIS Seems to be done*

## EXTERIOR

Weld snapped on rear bolt together plate - *take details for Bill*

cladding on rear severely damaged - *take details* *See pics*  
*x2 length of cladding*

gutter clips missing *ordered x4*

gable end join cover missing - *take details*  
*ordered* *Apex Cover*

Think  
this is  
same