

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE-----**DATE**-----

POSITION-----

WORK CODE: 413? LOG NO: PREOW-722 MAKE: Pre-Owned After Care MODEL: Vouge SIZE: 30 SERIAL NO: STOCK NO: Assigned to Isabel Smith	ADDRESS: (163) Diamond Farm Caravan & Camping Park Weston Road Brean TA8 2RL PITCH NO: 61 TEL:
---	--

Problem

Leak in the central heating system ✓
The leak has traced to underneath the van. Check the antifreeze levels as well.
Notes: Please call Dave (the owner) after the visit to let him know if any further work is required or if the issue has been completed. <i>Trayed no answer</i>
07708948793

Details of Work Done

No leaks underneath
 Bathroom rad valve leaking on spindle done ✓
 lounge rad valve leaking cross threaded nut done ✓

ARRIVAL TIME	1215
DEPARTURE TIME	230

DATE: 31/10/16	FITTER: Stone
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES