

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 32706 LOG NO: GW-4524 MAKE: Good Will MODEL: Loire SIZE: 35 X 12 SERIAL NO: 021974H STOCK NO: 32706 Assigned to Isabel Smith	ADDRESS: (86) Brightholme Holiday Park Coast Road Burnham on Sea TA8 2QY PITCH NO: 26 @ COAST HOLME TEL:
--------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------

Problem	
Dining room - Partition is coming away at the bottom	UPDATE INFO
Notes: Please can you reattach this.	

Details of Work Done
This is the backing board of seat where radiator is attached. At some point the bottom of this board has suffered water damage (leak from rad??) causing chipboard to swell. Cannot rectify requires new backing board see photos

ARRIVAL TIME	
DEPARTURE TIME	

DATE: 1/6/17	FITTER: MATT PEZZES
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES

This will take approx 2 hrs.