

ran out of time

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 33111 LOG NO: GW-4194 MAKE: Good Will MODEL: Burgundy SIZE: 35x12 SERIAL NO: 023666H STOCK NO: 33111 Assigned to Debbie Bartlett	ADDRESS: (341) Mother Ivey's Bay Holiday Park Trevoze Head Near Padstow PL28 8SL PITCH NO: Plot 497 TEL: 01841 520990
--	---

Problem

Mian bedroom Door stiff to open.

Notes:

* see photo of gap between bottom of door & frame.

Details of Work Done

Latch side wall is not fitted parallel - when door is shut it is touching on top of frame and a gap of approx 20mm is visible on bottom of door and frame - wall needs moving however this may result in a gap in vinyl or fixing holes visible. Need further advice to remedy

ARRIVAL TIME	
DEPARTURE TIME	

DATE: 9/5/17	FITTER: <u>MATT PETERS</u>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

	NOTES

Steve please can you advise Matt as to resolving this issue thanks. If another work sheet is need please let one of the girls know Thanks

This has been re-scheduled three times

* Couldn't do w/c 17/4 van let.