

Snagging

Lounge Area.

on order -

MIRROR

WALL PAPER GASH ABOVE MIRROR
RIGHT HAND TV CABINET DRAWER STICKING
CHIPS UNDER RUMMET.

KITCHEN AREA

reported -

SPLASHBACK COMING OFF.
~~BEHIND~~ BEHIND SPLASHBACK WALLPAPER
PATCHES OVER WALLPAPER.

RIGHT HAND SIDE BLIND STICKING + WOODEN
WORKTOP SURFACE JOINS NOT ACCEPTABLE
KNOBS ON COOKER FALLEN OFF
DOORS ALL NEED ALIGNMENT.

DOOR RUBBERS FALLING OFF
B/I/N DOOR UNDER SINK DOESNT SHUT.
RACK IN OVEN MISSING.

HINGE COVERS ON DOOR COMING OFF MOSTLY
UNDER SINK
LIGHTS UNDER CURTBARDS CEASED TO WORK.
ARCHITECTURE IN KITCHEN NEEDS ATTENTION

HALLWAY

ARCHITRAVE IN HALLWAY NEED ATTENTION

~~ARE~~ DO NO SIT RIGHT.

JOIN ABOVE SMALL BEDROOM DOOR BOUSED.

SMALL BEDROOM

INSIDE WALL PAPER RIPPED.

LEFT HAND SIDE DOOR OVER BED NEEDS ADJUSTING

TOILET

SHOWER FITTING NEEDS TIGHTENING.

NO SILICONE AROUND TOILET.

MAIN BEDROOM

COP BOARD ABOVE DRESSING TABLE HAS CRACKS

MARK AND DOES NOT NOT STAY OPEN

DRESSING TABLE DRAWER WORN ON EDGE

W/ASD&U FITTING CONES OFF.

DOORS ABOVE BED CHIPPED

WARDROBE DOOR MARKED.

WARDROBE DRAWERS CHIPPED.

BEDSIDE DRAWERS NEED ADJUSTING

DRESSING TABLE DRAWER NEED ADJUSTING.

BEN SUITE BATHROOM

SHOWER FITTING LOOSE.

SKIRTING CONE UNSTUCK.

NO SILICONE AROUND TOILET BASE.

OUTSIDE

GUTTERING LEAKING