

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 428 LOG NO: SWIFT-19197 MAKE: Swift MODEL: Whistler Lodge SIZE: 42 X 20 SERIAL NO: 023443H STOCK NO: 33354 Assigned to Summer Stangroom	ADDRESS: (882) Merley Court Holiday Park Wimborne Dorset BH21 3AA PITCH NO: 71 TEL:
---	---

<i>main</i>	Problem
Door has damaged docking plates – please see if you can resolve or say what parts are needed.	
<i>Partson site</i> ✓	
Notes:	
<i>Customer has discovered water leaking from tap under Sink which is making unit mouldy and possibly gone to soak</i>	

Details of Work Done
<i>in to floor under laminate floor and has now caused hump in floor to appear</i> <i>Tap is also loose on worktop does not seem to tighten</i> <i>Unit under Sink is also water damaged by swelling up</i>

ARRIVAL TIME	<i>1000</i>
DEPARTURE TIME	<i>1100</i>

DATE: <i>25/4/18</i>	FITTER: <i>Steve</i>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES