

LEAK!

16.

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 428 LOG NO: SWIFT-20997 MAKE: Swift MODEL: Moselle SIZE: 38 X 12 SERIAL NO: 026742H STOCK NO: 35102 Assigned to Summer Stangroom	ADDRESS: (489) Stowford Farm Meadows Berry Down Combe Martin EX34 0PW PITCH NO: 11 TEL:
--	---

Problem

In the en-suite bathroom sink there seems to be a small leak possibly from the cold water tap behind the sink pedestal. Please try to resolve.

Notes:

Details of Work Done

Connected van back onto water mains (drained down for winter)
Tested both hot/cold & waste in sink. Can find no evidence of any leaks. Tightened connections as a precaution.
Disconnected van from water mains and drained van down for winter

ARRIVAL TIME	13.15
DEPARTURE TIME	14.15

DATE: 10/12/18. FITTER: *MATT PETERS*

I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE

PARK/CUSTOMER SIGNATURE:

MATERIALS USED	NOTES