

WINDOW  
SEARCHED  
CLASS

## SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 35572 LOG NO: GW-7896 MAKE: Good Will MODEL: BORDEAUX SIZE: 38 x 12 SERIAL NO: 029127h STOCK NO: 35572 Assigned to Heather Barbieri	ADDRESS: (178) Edithmead Leisure Edithmead, Near Highbridge Burnham on Sea TA9 4HE PITCH NO: D25 TEL:
---	---

### Problem

The gutters near the side door and outside the kitchen window are still leaking it looks to me that the guttering has been cut about half an inch to short so where the 2 join it is just on the clip rather than fully on.

Notes: The gutters near the side door and outside the kitchen window are still leaking despite attempts to fix this. I did have a look at one and it looks to me that the guttering has been cut about half an inch to short so where the 2 join it is just on the clip rather than fully on.  
PLEASE TAKE THE REQUIRED PART FROM THE TOP SORES

### Details of Work Done

2 lengths of gutter replaced.  
5L + of water poured in gutter  
AND NO LEAKS! COMPLETE

ARRIVAL TIME	13-00
DEPARTURE TIME	14-00

DATE: 1/8/19 FITTER: Tom J  
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE  
PARK/CUSTOMER SIGNATURE:

MATERIALS USED	NOTES

