

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE----- DATE-----**

**POSITION-----**

WORK CODE: 428 LOG NO: SWIFT-22889 MAKE: Swift MODEL: Moselle Lodge SIZE: 40x13 SERIAL NO: 029278H STOCK NO: 36546 Assigned to Adrienne Barwell	ADDRESS: (413) Warren Bay Holiday Park Watchet Minehead TA23 0JR  PITCH NO: 63  TEL:
--	--

Problem
Bath needs resealing/mastic needs refitting as bath is leaking ✓
Notes:

Details of Work Done

ARRIVAL TIME	
DEPARTURE TIME	

DATE: 19/9/19	FITTER: Steve Tom
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
<b>PARK/CUSTOMER SIGNATURE:</b>	

MATERIALS USED	NOTES

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE**-----**DATE**-----

**POSITION**-----

WORK CODE: 428 LOG NO: SWIFT-22647 MAKE: Swift MODEL: moselle lodge SIZE: 40 x 13 SERIAL NO: 029278h STOCK NO: 36546 Assigned to Claire Folland	ADDRESS: (413) Warren Bay Holiday Park Watchet Minehead TA23 0JR  PITCH NO: ... <b>63</b>  TEL:
--	---

**Problem**

Kitchen Fire extinguisher pin broken - <i>Customer Says not ?</i>
Notes:

**Details of Work Done**

<p style="font-size: 1.2em;"><i>015857 87 floor kitchen</i></p> <p style="font-size: 1.2em;"><i>Master bed Bath leaking - Legs</i></p> <p style="font-size: 1.2em;"><i>Kitchen Board-batter Shower legs loose</i></p> <p style="font-size: 1.2em;"><i>Seal door - adjustment</i></p>
--

ARRIVAL TIME	
DEPARTURE TIME	

<b>DATE:</b> <i>12/9/19</i>	<b>FITTER:</b> <i>Steve</i>
<b>I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE</b>	
<b>PARK/CUSTOMER SIGNATURE:</b>	

MATERIALS USED	NOTES

Warren bay Holiday Park 20/08/2019  
 SWIFT-22647  
 Swift Moselle Lodge  
 029278H

Kitchen Fire Extinguisher