

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE-----**DATE**-----

POSITION-----

WORK CODE: 428 LOG NO: SWIFT-23841 MAKE: Swift MODEL: whistler lodge SIZE: 41x20 SERIAL NO: 028774h STOCK NO: 35548 Assigned to Claire Folland	ADDRESS: (178) Edithmead Leisure Edithmead, Near Highbridge Burnham on Sea TA9 4HE PITCH NO: d57 TEL:
---	---

Problem

leak in the roof front left hand corner of the living room, please can you attend and see if you can fix

The owner of the above lodge came to see me on Sunday and I popped into his lodge. He has a leak in the roof front left hand corner of the living room.

I know we have had a lot of call outs recently that have been condensation but I believe this is possibly a leak, there was a puddle of water on the floor that the owner unfortunately cleaned up but also when you touch the roof in this corner it is wet and the silicone has started going brown.

Please arrange for swift to come out ASAP Please to check this out.

Notes:

*Dent in roof allowing gap have sealed
 + bottom edge of roof tipped up allowing water to be*

Details of Work Done

Plum underneath. Have bent roof edge down

ARRIVAL TIME	
DEPARTURE TIME	

DATE: <i>18/2/20</i>	FITTER: <i>Steve</i>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES