

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE _____ **DATE** _____

POSITION _____

| | |
|---|--|
| WORK CODE: 32492 LOG NO: 311-2384 <i>Swift - 26154</i> MAKE: Good Will MODEL: Moselle Lodge SIZE: 40 x 13 SERIAL NO: 022266H STOCK NO: 32492 Assigned to Heather Barbieri | ADDRESS: (555) Trewince Farm Holiday Park St Issey Wadebridge PL27 7RL PITCH NO: 78 TEL: |
|---|--|

Problem

Master Bedroom - The top right corner of the window is leaking in water where the frame fits the body.

Notes: Good morning. Our lodge is at trewince farm st issey plot 78 bay view. We have a recurrence of the water ingress problem resulting in wet carpet this time so it would appear that the remedial work hasn't worked. We would like the problem attended to as we are concerned about the damage water can do. Thank you. Jacqueline King

Details of Work Done

Steps has checked & sealed

| | |
|----------------|---|
| ARRIVAL TIME | / |
| DEPARTURE TIME | / |

| | |
|---|----------------------------|
| DATE: <i>9/1/20</i> | FITTER: <i>[Signature]</i> |
| I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE | |
| PARK/CUSTOMER SIGNATURE: | |

| MATERIALS USED | NOTES |
|----------------|-------|
| | |
| | |