

Emailed to Duncan

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: CHARGEABLE LOG NO: CHARGE-4883 MAKE: Chargeable Parts MODEL: coworth SIZE: 36 x 12 SERIAL NO: 2011960 STOCK NO: 39047 Assigned to Heather Barbieri	ADDRESS: Porthilly Caravan Park Rock Wadebridge PL27 6JX PITCH NO: TEL: 01208 862862 / 07890034489 (Tim's mobile)
--	---

Problem

Transport Damage Transport company was WS Services wsserviceshulltd@gmail.com

Notes: **WS Services wsserviceshulltd@gmail.com TO BE CHARGED**

M/Bed Top Shelf Split with damage from outside

Details of Work Done

w/s middle back panel 6'600 x 1245

See pics

Could possible have half 3 room approx.

but customer would rather have full panel

ARRIVAL TIME	
DEPARTURE TIME	

1/2 day 2 men

DATE:	FITTER:
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES

Porthilly Caravan Park
CHARGE-4883
ABI Coworth
2011960

Transport Damage

*This is
Separate claim
to one above
This is due
to tree
branch damage*