

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 40658 LOG NO: GW-9943 MAKE: Good Will MODEL: LOIRE SIZE: SERIAL NO: 042809H STOCK NO: 40658 Assigned to Heather Barbieri	ADDRESS: Hentervene Crackington Haven Bude EX23 0LF PITCH NO: 4 TEL: 01840230365
--	--

Problem

roof damage at factory to be looked at when van PDI'd

Notes: Hello Martyn,
 Swift arrived this morning. Had a chat with the lorry driver, who showed me some photos of the caravan before he loaded it. Swift rushed a repair before they brought it to us. I am concerned about the integrity of the van. Looks like a gutter and fascia repair, but the corner pieces and the central badged piece is wonky.
 Someone needs to come out and take a look/straighten it.

Kind regards,
 Steve.

Details of Work Done

Requires 1x Roof sheet on front O/S to be replaced to allow correct fitting of bargeboards

(1x man + Tower required)

ARRIVAL TIME	1115
DEPARTURE TIME	1130

DATE: 28/6/23	FITTER: Duncan T
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES