

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

| | |
|---|--|
| <p>WORK CODE: 403 LOG NO: QUOT-3811 MAKE: Willerby MODEL: Rio Gold SIZE: SERIAL NO: STOCK NO: 2011 Assigned to Duncan Thomson</p> | <p>ADDRESS: Golden Sands Holiday Park (Park Holidays) Week Lane Dawlish EX7 0LZ PITCH NO: H100 TEL: 01626 244747</p> |
|---|--|

Problem

| |
|---|
| Quote to replace damaged panels |
| Customer Called (Paul Southgate) 07785928970 Car has driven into caravan causing panel and chassis damage |
| Notes: Park have keys for assess as customer also advised wallboard needs attention. <i>No damage inside or is behind Shower cubicle Cubicle look ok</i> |

Details of Work Done

| |
|--|
| <i>O/S middle Bottom panel : 3.400 x 895 Floor joist timber 120mm x 25 x 2000mm Steel outriggers bent back</i> |
|--|

| | |
|----------------|--|
| ARRIVAL TIME | |
| DEPARTURE TIME | |

*maybe some repair behind panel
+ Slaps to remove*

| | |
|---|----------------|
| DATE: | FITTER: |
| I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE | |
| PARK/CUSTOMER SIGNATURE: | |

| MATERIALS USED | NOTES |
|----------------|-------|
| | |
| | |