

## Coastholme TA8 2QY

### Engineer Assessment Form

Assessment Completed By:	Stewart No 26
Date of Assessment:	
Time of Arrival:	
Time of Departure:	
JIRA Reference	Quot-3859
SAGE Quote No.	
Work Code	
Van Make	swift
Van Model	2016 Loire
Van Serial Number	021974H
Van Stock Number	32706
Van Size	35x12
<b>Quote Information</b>	<b>Panel damage on rear corner of van</b>
Description of the Issue Including the Following: <ul style="list-style-type: none"><li>• Internal or External?</li><li>• Which Room of the Caravan/ Which Panel?</li><li>• Which Parts does the issue affect?</li><li>• Plus any other useful information</li></ul>	w/s Bottom panel 3.500 x 440 w/s mid panel 3.500 x 850 + Corner capping + backing piece will need M/Bed window remaining + just Skirting rail, fixed on outside No Damp inside M/Bed
What is the cause of the issue?	2 men 1 Day