

Berry Barton EX12 3BD

Engineer Assessment Form

Assessment Completed By:	
Date of Assessment:	
Time of Arrival:	
Time of Departure:	
JIRA Reference	Quot-3874
SAGE Quote No.	
Work Code	
Van Make	Bk
Van Model	Lulworth plot 34
Van Serial Number	
Van Stock Number	
Van Size	
Quote Information	Roof leaking in kitchen area, insurance company has asked customer for quote
Description of the Issue Including the Following: <ul style="list-style-type: none">• Internal or External?• Which Room of the Caravan/ Which Panel?• Which Parts does the issue affect?• Plus any other useful information	<p>This is ridge vent leaking + possibly foam around. probably just needs a rescal have pres</p> <p>Not planning to do anything inside ceiling board + central ceiling woodwork slightly damaged</p>
What is the cause of the issue?	2 hours 1 man