

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 403 LOG NO: QUOT-3822 MAKE: Quotes MODEL: Coworth SIZE: 36x12 SERIAL NO: 2010342 STOCK NO: 37316 Assigned to Duncan Thomson	ADDRESS: JB Old Ltd, t/a Treyarnon Bay Caravan Park St Merryn Padstow PL28 8JP PITCH NO: A23 TEL: 01841 520681 // 01841 520653
---	--

Problem

that the caravan has had a valve issue in the shower and consequently, water has been coming out of the thermostatic bar, and somehow, through the wall into the lounge. This has caused significant flooding damage

Notes:

2.5 Days

Details of Work Done

Completed

ARRIVAL TIME	
DEPARTURE TIME	

DATE: <i>29/12/24</i>	FITTER: <i>Duncan & Steve</i>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES