

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 403 LOG NO: QUOT-3921 MAKE: Swift MODEL: Moselle SIZE: 40x12 SERIAL NO: 021228h STOCK NO: 32445 Assigned to Charleen Sibley	ADDRESS: North Upton Farm Bantham Kingsbridge TQ7 3AB PITCH NO: Jackie Day TEL: 01548 560508
---	--

Problem

<p>Quote to find and reseal leaks from rear bargeboard</p> <p>From our assessment have found most probable cause is a failed seal under the bargeboards and silicone above the windows, this quote is only to find and fix the leaks and doesn't cover any internal repairs currently.</p>
<p>Notes: When carrying out repairs to also assess internal damage and make note of what is required for an internal quote. (Main Bedroom and Ensuite)</p> <p style="font-size: 1.2em; margin-top: 10px;"><i>Customer will keep Main bed Ceiling if not readily available</i></p>

Details of Work Done

<p>Main Bed :- Replace wall board on end wall above shelf unit " wallboard on wall around window to floor Replacement dressing table top required</p> <p>Ensuite :- Replace wall boards around window Add extra joists to floor as floor is sagging possible sand joint in floor</p>
--

ARRIVAL TIME	
DEPARTURE TIME	

DATE: <i>29/8/24</i>	FITTER: <i>Steve</i>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES

2 men 1 Day 3½ wall boards
 x1 Dressing table top
 3m 4x2 extra joist

Main Bedroom Ceiling Shrink back
 Small amount of damage may be able
 to improve when doing work
 (This is single T+G planked ceiling)