

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE**-----**DATE** 7.8.14

**POSITION**-----

WORK CODE: <u>29143</u> LOG NO: RET-9 MAKE: Retrofit MODEL: Bordeaux SIZE: SERIAL NO: 13767h STOCK NO: 29143	ADDRESS: Trethias Trethias Farm Caravan Park Treyarnon Bay St Merryn Padstow CORNWALL PL28 8PL  PITCH NO: <u>D11</u> TEL:
--	---

**Problem**

Wall vent weather seal required to finish off the fitting of the extractor unit, please fit replacement vent cover

Notes:

**Details of Work Done**

NOTE STILL NEEDED - SLAT FOR DINING ROOM BLIND  
 COUPLER STRIP (BIFOLD) FOR ENSUITE  
 TO COUPLER MARK ON WALL  
  
 ALSO WHATS HAPPENING ABOUT EXTRACTOR  
 THROUGH ROOF ??

ARRIVAL TIME	
DEPARTURE TIME	

DATE:	FITTER:
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
<b>PARK/CUSTOMER SIGNATURE:</b>	

MATERIALS USED	NOTES

Bi fold strip for RET9 = 1711572