

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE-----**DATE** 7.8.14

POSITION-----

WORK CODE: LOG NO: QUOT-1384 MAKE: Quotes MODEL: Atlas fanfair SIZE: SERIAL NO: None given STOCK NO:	ADDRESS: Treynon Bay Trethias Farm Caravan Park Treynon Bay St Merryn Padstow CORNWALL PL28 8PL PITCH NO: J3 Mr mike Menhenhit TEL: site 01841 520681 – owner 07841 465780
--	--

Problem

<p>Shower in the bathroom has a crack by the waste(water drainage hole) the owner has said that it's not the skin it a tray that is cracked.- please can we access for a quote The owner want us to do the work asap,</p>
<p>Notes: I have said that we would need to look at this to see what shower tray would be needed then we would be able to e-mail or call him with a quote as we would need to take take prior to work/ parts on order</p>

Details of Work Done

--

ARRIVAL TIME	<u>12.15</u>
DEPARTURE TIME	<u>12.30</u>

DATE:	FITTER:
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES