

## SURF BAY LEISURE AFTERSALES WORKSHEET

**I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:**

**SIGNATURE**-----**DATE**-----

**POSITION**-----

WORK CODE: 408 LOG NO: GW-417 MAKE: Good Will MODEL: Ruby SIZE: 38x12 SERIAL NO: AT010788/05 STOCK NO: 29853	ADDRESS: Old Coastguard Holiday Park Ltd <b>Burton Bradstock</b> <b>Nr Bridport</b> <b>DORSET</b> <b>DT6 4RL</b>  PITCH NO: TEL: 01308 897223
--	--

**Problem**

PDI reports Bottom light shade screw missing in the twin bedroom - *no parts to fit*  
 PDI reports floor covering has been punctured by the carpet join strip - *needs repair*  
 PDI reports bath front fascia has a gap in it on the top right hand side  
 PDI reports bath front fascia has a gap in it on the top right hand side  
 PDI reports flaw in the fabric of the corner cushion of settee - *needs new cover*  
 PDI reports sink unit kicking board has no clips - *need 6 clips*  
 PDI reports dining table has two broken legs - *only one leg supplied one more needed*  
 dining table only has three legs table

Notes:

**Details of Work Done**

ARRIVAL TIME	<i>10:30</i>
DEPARTURE TIME	<i>11:15</i>

**DATE:** *24/10/14*      **FITTER:** *Steve*

**I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE**

**PARK/CUSTOMER SIGNATURE:**

MATERIALS USED	NOTES