

Priority

## SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

|  |  |
|--|--|
| WORK CODE: 403<br>LOG NO: QUOT-1289<br>MAKE: Quotes<br>MODEL: Burgundy<br>SIZE: 35x10x3<br>SERIAL NO: 6157h<br>STOCK NO: | ADDRESS: Morngate Holiday Park<br>Morn Gate Caravan Park<br>Bridport Road<br><br>Dorchester<br>DORSET DT2 9DS<br><br>PITCH NO:<br>TEL: |
|--|--|

Problem

Panel damage reported by Linda at Bridport – please replace window side front, mid and bottom panels

Notes: 3x panels.  
2 men.

Too windy today

Details of Work Done

|                |  |
|----------------|--|
| ARRIVAL TIME   |  |
| DEPARTURE TIME |  |

|  |         |
|--|---------|
| DATE:  | FITTER: |
| I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE |         |
| PARK/CUSTOMER SIGNATURE:                                       |         |

| MATERIALS USED | NOTES |
|----------------|-------|
|                |       |
|                |       |