

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE-----**DATE**-----

POSITION-----

WORK CODE: LOG NO: QUOT-1289 MAKE: Quotes MODEL: Burgundy SIZE: 35x10x3 SERIAL NO: 6157h STOCK NO:	ADDRESS: Morn Gate Caravan Park (340) Bridport Road Dorchester DT2 9DS PITCH NO: TEL:
--	--

Problem

Panel damage reported by Linda at Bridport – please replace window side front, mid and bottom panels

Notes:

It was too windy to complete this work last time (old worksheet attached)

Details of Work Done

ARRIVAL TIME	1030
DEPARTURE TIME	300

DATE: 1/12/14	FITTER: Steve / Keith
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES

Priority

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 403 LOG NO: QUOT-1289 MAKE: Quotes MODEL: Burgundy SIZE: 35x10x3 SERIAL NO: 6157h STOCK NO:	ADDRESS: Morningside Holiday Park Morn Gate Caravan Park Bridport Road Dorchester DORSET DT2 9DS PITCH NO: TEL:
--	---

Problem

Panel damage reported by Linda at Bridport – please replace window side front, mid and bottom panels

Notes: 3x panels.
2 men.

Too windy today

Details of Work Done

ARRIVAL TIME	
DEPARTURE TIME	

DATE:	FITTER:
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES