

WORK CODE 404

Please pass to Mo after Scanning

**SURF BAY LEISURE AFTERSALES ASSESSMENT SHEET**

Completed By:	KJL	
Arrival Time	12-15	
Departure Time:	1-00	
Work Code		Address:
Log No.	QUOT-1479	Trethiggey Caravan Park (561)
Make	Quotes	Quintrell Downs
Model	Willerby Rio	Newquay
Size		TR8 4LG
Serial No.		
Stock No.		
Pitch No.	OAK	Tel:01637 877672
Notes:	<p>WATER HAS BEEN LAYING ON BED ROOM/WARDROBE FLOOR          LOOKS LIKE IT HAS COME FROM SHOWER UNDER VINYL / SHOWER</p>	
Description:	<p>There is a leak but the site do not know where it is from</p>	
Parts Required:	<p>COULD BE LEAK FROM SHOWER          SOME GAPS IN ENCLOSURE/SILICON          OR FIBER PIPES TO SHOWER MIXER          OR PIPE JOINTS UNDER FLOOR TO SHOWER MIXER</p>	
Measurements:	<p>* IMPORTANT - WILL NEED VINYL OR BOARDS TO CHECK UNDER BATH AS</p>	
Estimated Time:	<p>SITBN and MUD</p>	
Man Power:	<p>1 MAN 3 HRS - REMOVE + RESCAL SHOWER LEAK + CHECK WASTE CHECK PLUMBING UNDER BATH</p>	
Photos Taken?	<p>VAN + BACK OF SHOWER MIXER</p>	