

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE 4.2.15

POSITION-----

WORK CODE: 404 LOG NO: QUOT-1479 MAKE: Quotes MODEL: Willerby Rio SIZE: SERIAL NO: STOCK NO:	ADDRESS: Trethiggey Caravan Park (561) Quintrell Downs Newquay TR8 4LG PITCH NO: <u>OAK</u> TEL:
--	---

Problem

Find and repair the leak, then re-seal the shower with silicon/mastic

Notes:

✓

Details of Work Done

2 POTTING S BATHING SHOWER
LEAKING

ARRIVAL TIME	<u>11:15</u>
DEPARTURE TIME	<u>1:30</u>

DATE:

FITTER:

I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE

PARK/CUSTOMER SIGNATURE:

MATERIALS USED	NOTES