

SURF BAY LEISURE AFTERSALES WORKSHEET

I AUTHORISE SURF BAY LEISURE TO ENTER THE CARAVAN LISTED BELOW:

SIGNATURE----- DATE-----

POSITION-----

WORK CODE: 30106 LOG NO: PREOW-646, <i>PREOW-618</i> MAKE: Pre-Owned After Care MODEL: Brisbane SIZE: 37x12 SERIAL NO: STOCK NO: 30106	ADDRESS: Warren Farm Holiday Centre warren road Brean Sands Near Burnham on Sea TA8 2RP PITCH NO: 17 sunnyside Mrs Miller TEL:
--	--

Problem

kitchen vent leaking, ceiling boards bubbling around the vent, please can you have a look and see if you can sort <i>oven door seal missing, please fit</i>
Notes: <i>Roof vent seal leaking Have rescaled</i>

Details of Work Done

--

ARRIVAL TIME	145	<i>145</i>	
DEPARTURE TIME	300	<i>300</i>	

DATE: <i>1/4/15</i>	FITTER: <i>Steve</i>
I AM HAPPY WITH THE WORK CARRIED OUT TODAY BY SURF BAY LEISURE	
PARK/CUSTOMER SIGNATURE:	

MATERIALS USED	NOTES